Touch (knock) sensor with Piezo

If you want to make a simple touch sensor but you don't have the fancy ones around you can also use a piezo element, which come with a lot of basic arduino starter sets.

What you need:

piezo element B400%2FEKULIT-190051.jpg?type=Product&	breadboard breadboard-afmetingen-81-x-55-x-8mm.jpg	resistor 1 M ohm images?q=tbn:ANd9GcTBA4twFjVplLxCI
piece of paper tape shopping?q=tbn:ANd9GcRQQMlNLQViZ2	some male/male jumper wires PP1b8sfp-hSPZUXq4crtlXjPWIL6NVMVDzg	IMaPLBn3jHA5zJfmCBD8wS55BpYr2IThg7

This video explains it all. To make the input visual, open the serial Monitor from the Tools menu.

https://www.youtube.com/embed/X3XXRZMBPO0?si=h6yr3887zh71YfDZ

Revision #4
Created 2025-02-12 13:05:45 UTC by Simone
Updated 2026-09-29 12:50:29 UTC by Simone